






















N.	Timeline	PNR	TNR	TNR-Intern	Planmenge	Rohrstutzen	Kalibrierung	Package	Needed Tool-Sets [Quantity]	Feasibility	Ø [mm]	WT [mm]	CLR [mm]	n° bend	approx length [mm]	Cut length needed	Δ length/cut length	Concept
1	MLB LK2	10.015.14.20	06R121491H-1	04012578	168 360 Stk.		2x Ø 16 ±0,05	1	1		16,00 [mm]	1,00 [mm]	24,00 [mm]	7	357,00 [mm]		-357,00 [mm]	
2	MLB LK2	10.015.14.20	06R121491H-2	04014303	168 360 Stk.	VW 78007 Form B aber Längentoleranz mit ± 1mm	1x Ø 10 ±0,05	1	1		10,00 [mm]	1,00 [mm]	15,00 [mm]	1	71,00 [mm]		-71,00 [mm]	
3	MLB LK2	10.015.14.20	06R121491H-3	04012708	168 360 Stk.	VW 78007 Form B aber Längentoleranz mit ± 1mm		1	1		20,00 [mm]	1,00 [mm]	0,00 [mm]	0	120,00 [mm]		-120,00 [mm]	
4	MLB LK2	10.016.14.20	06R121492N-1	04014304	168 360 Stk.		Ø 16 ±0,05	1	1		16,00 [mm]	1,00 [mm]	24,00 [mm]	4	148,90 [mm]		-148,90 [mm]	
5	MLB LK2	10.016.14.20	06R121492N-2		168 360 Stk.	VW 78007 Form B aber Längentoleranz mit ± 1mm	1x Ø 10 ±0,05	1	1		10,00 [mm]	1,00 [mm]	0,00 [mm]	0	41,80 [mm]		-41,80 [mm]	
6	MLB LK2	10.017.14.20	06R121497K-1	04012572	168 360 Stk.	VW 78007 Form B aber Längentoleranz mit ± 1mm	Ø 16 ±0,05	1	1		16,00 [mm]	1,00 [mm]	24,00 [mm]	2	144,60 [mm]		-144,60 [mm]	
7	MLB LK2	10.018.14.20	06R145735N-1	04012580	168 360 Stk.	VW 78007 Form B aber Längentoleranz mit ± 1mm	Ø 16 ±0,05	1	1		16,00 [mm]	1,00 [mm]	24,00 [mm]	1	77,60 [mm]		-77,60 [mm]	
8	MLB LK2	10.018.14.20	06R145735N-2	04014306	168 360 Stk.	VW 78007 Form B aber Längentoleranz mit ± 1mm	Ø 16 ±0,05	1	1		16,00 [mm]	1,00 [mm]	24,00 [mm]	2	138,60 [mm]		-138,60 [mm]	
9	MLB LK2	10.019.14.20	06R145140A-1	04012590	168 360 Stk.	04008319	Ø 8 ±0,05	1	1		8,00 [mm]	1,00 [mm]	12,00 [mm]	5	259,70 [mm]		-259,70 [mm]	
10	MLB LK2	10.019.14.20	06R145140A-2	04012589	168 360 Stk.	04008319	Ø 8 ±0,05	1	1		8,00 [mm]	1,00 [mm]	12,00 [mm]	3	135,70 [mm]		-135,70 [mm]	
21	FUEL EA888	48.009.27.21	06R133986C		77 219 Stk.	SAE	Ø 10 ±0,05	1	1		10,00 [mm]	1,00 [mm]	25,00 [mm]	6	388,90 [mm]		-388,90 [mm]	
22	MQB LK3	10.025.14.20	06U145735AD-1	04016213	74 520 Stk.	VW 78007 Form B aber Längentoleranz mit ± 1mm		2	2		16,00 [mm]	1,00 [mm]	24,00 [mm]	2	112,90 [mm]		-112,90 [mm]	
23	MQB LK3	10.025.14.20	06U145735AD-2	04016211	74 520 Stk.	VW 78007 Form B aber Längentoleranz mit ± 1mm	Ø 16 ±0,05	2	2		16,00 [mm]	1,00 [mm]	24,00 [mm]	1	60,10 [mm]		-60,10 [mm]	

24	MQB LK3	10.021.14.20	06U121492AA-1	04016208	74 520 Stk.	VW 78007 Form B aber Längentoleranz mit ± 1mm	Ø 16 ±0,05	2	2		16,00 [mm]	1,00 [mm]	24,00 [mm]	1	110,40 [mm]		-110,40 [mm]	
25	MQB LK3	10.021.14.20	06U121492AA-1	04016209	74 520 Stk.			2	2		10,00 [mm]	1,00 [mm]	15,00 [mm]	1	60,10 [mm]		-60,10 [mm]	
28	MQB LK3	10.023.14.20	06U121497R	04016210	74 520 Stk.	VW 78007 Form B aber Längentoleranz mit ± 1mm	Ø 16 ±0,05	2	2		16,00 [mm]	1,00 [mm]	24,00 [mm]	2	147,40 [mm]		-147,40 [mm]	
29	MQB LK3	10.027.14.20	06U145140K-1	04016214	74 520 Stk.	04008319	Ø 8 ±0,05	2	2		8,00 [mm]	1,00 [mm]	12,00 [mm]	4	209,90 [mm]		-209,90 [mm]	
30	MQB LK3	10.027.14.20	06U145140K-2	04016217	74 520 Stk.	04008319	Ø 8 ±0,05	2	2		8,00 [mm]	1,00 [mm]	12,00 [mm]	4	211,30 [mm]		-211,30 [mm]	

31	DL382	46.688.35.12	OCK325319A	K8000292	883 200 Stk.			3	1		10,00 [mm]	1,00 [mm]		7	238,30 [mm]		-238,30 [mm]	
32	DL382	46.688.35.12	OCK325319A	K8000292	883 200 Stk.			3	1		10,00 [mm]	1,00 [mm]		4	238,30 [mm]		-238,30 [mm]	
33	B57D30X2X3	23.001.10.21	782470404	K8001102	227 040 Stk.			2	1		18,00 [mm]	1,00 [mm]	25,00 [mm]	4	180,96 [mm]		-180,96 [mm]	
34	B57D30X2X3	23.001.10.21	782470404	K8001103	227 040 Stk.			2	1		15,00 [mm]	1,00 [mm]	20,00 [mm]	4	187,36 [mm]		-187,36 [mm]	